
SUTTON Assembly Instructions

9186-22H 9186-21H KING HEADBOARD, GREY QUEEN HEADBOARD, GREY



Parts List



#1 x1pc Headboard



#2 x1pc Headboard Left Leg



#3 x1pc Headboard Right Leg



#4 x1pc Support Rail

Hardware List



#A x4pcs
Bolt Ø5/16"x57mm




#B x2pcs Bolt Ø5/16"x40mm



#C x6pcs Lock Washer Ø5/16"



#D x6pcs Flat Washer Ø5/16"




#E x1pc Allen Key 4mm

* Hardware place at the back of Headboard

Sutton Queen Assembly Instructions

9186-21FR QUEEN FOOTBOARD, RAILS, 4 SLATS, SUPPORTS LEGS, **GREY**




OPTION 2

Parts List




#1 x1pc Headboard (In Other Carton)



#4 x2pcs Side Bed Rail



#2 x1pc Footboard



#5 x4pcs Straight Slat



#3 x2pcs Footboard Leg



#6 x8pcs Support Leg

Hardware List



#A x2pcs Bolt Ø5/16"x57mm



#C x2pcs Flat Washer Ø5/16"



#B x2pcs Lock Washer Ø5/16"



#D x1pc Allen Key 4mm



#E x8pcs Screw #8x30mm

Assembly Instructions STEP 1 #E #A #C #D #3 #2 STEP 2: OPTION 1 STEP 2: OPTION 2 <u>#</u>1 <u>#1</u>

Page 2 of 4

#2


#4

#4


#2

Assembly Instructions

STEP 3: OPTION 1




STEP 3: OPTION 2




Page 3 of 4

Assembly Instructions

COMPLETED: OPTION 1




COMPLETED: OPTION 2




Assembly Instructions

STEP 1



STEP 2





WARNING: To avoid serious personal injury:

- · Carefully and strictly follow assembly instructions. Improper assembly of furniture can result in structural failure, instability of the product, or tip-over.
- · Monitor and carefully control the assembly components. These include small parts and hardware that may present a choking hazard to small children. Bob's furniture should be assembled only by responsible adults and children should not be involved in the assembly process.
- · Where provided, wall mounting hardware should always be used as prescribed in these instructions to anchor furniture to wall. Proper use of the wall mounting hardware can significantly reduce the potential for furniture tip-over and crushing injuries.